

5. CONCLUSIONS

The result of this research is as follows:

1. the natural frequency decreases both experiment and simulation tested as crack depth increases,
2. the first harmonic components decrease linearly as crack depth increases; in contrast, the second harmonic components increase quadratically as crack depth increases,
3. the orbit shape changes, especially at 3 mm crack depth, the double loop symptom appears.

