

DAFTAR PUSTAKA

- [1] D.A. Ameyaw. (2014). Crack Detection in Shaft Using Vibration Measurement and Analysis (Master's Thesis). Department of Mechanical Engineering, Collage of Engineering, Kwame Nkrumah University.
- [2] A.K. Jain, V. Rastogi, A.K. Agrawal. (2015). *Experimental Investigation of Vibration Analysis of Multi-Crack Rotor Shaft*. Department of Mechanical, Production, Industrial and Automobile Engineering, Delhi Technological University
- [3] G.S. Chaure & D.Y. Shahare. (2015). Crack Detection Techniques in Rotating Shaft. *Journal of Pure and Applied Research in Engineering and Technology*, 3(9), 272-278
- [4] T. Zhou, Z. Sun, J. Xu, & W. Han. (2005). Experimental Analysis of Cracked Rotor. *Journal of Dynamic Systems, Measurement, and Control*, 127, 313-320.
- [5] A.A. Mohamed. (2011). Monitoring Fatigue Crack Stages in a High Carbon Steel Rotating Shaft Using Vibration. *10*, 130-135
- [6] J-J. Sinou, & A.W. Lees. (2005). The Influence of Cracks in Rotating Shafts. *Journal of Sound and Vibration*, 285(4-5), 1015-1037
- [7] M.R. Fadilah. (2021). Analisis Tegangan dan Frekuensi Pribadi pada Sistem Rotor dengan Retakan Poros (Tugas Akhir). Jurusan Teknik Mesin, Fakultas Teknik, Universitas Andalas
- [8] I.W. Mayes, W.G.R. Davies, Analysis of the response of a multi-rotor-bearing system containing a transverse crack in a rotor, *Journal of Vibration, Acoustics, Stress, and Reliability in Design* 106 (1984) 139–145.
- [9] M-C. Wu, S-C. Huang, Vibration and crack detection of a rotor with speed-dependent bearings, *International Journal of Mechanical Science* 40 (6) (1998) 545–555.

- [10] O.S. Jun, H.J. Eun, Y.Y. Earmme, C.W. Lee, Modellingand vibration analysis of a simple rotor with a breathing crack, Journal of Sound and Vibration 155 (2) (1992) 273–290
- [11] A. Fahlefi. (2019). *Pengaruh Jarak Tumpuan Terhadap Frekuensi Pribadi Sistem Poros Rotor Overhung Melalui Eksperimen dan Simulasi Autodesk Inventor* (Undergraduate's Thesis). Jurusan Teknik Mesin, Fakultas Teknik, Universitas Andalas
- [12] L.F. Ramos, G.D. Roeck, P.B. Lourenco, & A. Campos-Costa. (2014). Damage Identification based on Vibration Measurements Applied to Masonry Structures. *Proceedings of ISMA2006.* 925-940
- [13] Y. Cheng. (2013). Multi-Wave and Hybrid Imaging Techniques: A New Direction for Nondestructive Testing and Structural Health Monitoring. *Journal of Sensors, 13,* 16146-16190
- [14] G.R. Sabnavis, G., Kirk, M., Kasada, & D. Quinn. (2004). Cracked Shaft Detection and Diagnostica: A Literature Review. *The Shock and Vibration Digest.*
- [15] N.N.. Displacement Sensor. Industrial Automation Accessed 20th February 2020. Retrieved from <http://www.ia.omron.com/support/guide/56/introduction.html>.
- [16] A. Gunawan. (2022). Kaji Eksperimental Faktor Skala Terhadap Frekuensi Pribadi Pada Cantilever Beam. Jurusan Teknik Mesin, Fakultas Teknik, Universitas Andalas.
- [17] N.N.. Vibration Proximity Sensor Jamaica. VRSensor Accessed. 20th February 2020. Retrieved from https://vr-sensor.com/supplier/vibration_proximity_sensor_jamaica_34069.html
- [18] N.N.. picoscope 4424 KIT. Farnel an Anvent Company. Accessed 20th February 2020. Retrieved from <https://uk.farnell.com/pico-technology/picoscope-4424-kit/oscilloscope-pc-high-precision/dp/1669213>

- [19] A.P. Wijaksono. (2020). *Experimental Study of The Nose Landing Gear Stiffness and Mass Variation on The Acceleration Response Amplitude* (Tugas Akhir). Jurusan Teknik Mesin, Fakultas Teknik, Universitas Andalas.
- [20] N.N.. Catu Daya DC. Pengertian Catu Daya Diakses 20 November 2021. Diperoleh dari <https://serviceacjogja.pro/pengertian-catu-daya/>
- [21] N.N... TaffSTUDIO LCD Digital Laser Photo Tachometer 2.5-100000 RPM - DT-2234C+ - Black. Jakarta Notebook. Diakses 20 November 2021. Diperoleh dari <https://www.jakartanotebook.com/taffstudio-lcd-digital-laser-photo-tachometer-2.5-100000-rpm-dt-2234c-black>
- [22] M.K. Ibrahim. (2020). *Dynamic Analysis of Several Aircraft Winglets with Computational and Experimental Comparisons* (Tugas Akhir). Mechanical Engineering Department, Faculty of Engineering, Universitas Andalas.
- [23] R.F. Hadi. (2021). *Vibration Signal Analysis of a Cracked Rotating Shaft in Overhung Rotor Model* (Tugas Akhir). Mechanical Engineering Departement, Faculty of Engineering, Universitas Andalas.
- [24] E. Purwanto. Tinjauan Kekakuan pada Kolom Retrofit dengan Pengekangan Carbon Wrapping. Jurusan Teknik Sipil, Fakultas Teknik, Universitas Sebelas Maret